

- () 6. Wire all 12 jacks and pin 1 of P2 to the appropriate point on the board near the edge connector corresponding with the letters on the wiring diagram.

THIS COMPLETES ASSEMBLY OF YOUR AR323 DUAL MIXER.

There is no calibration or test procedure required. Your AR 323 Dual Mixer is now ready to use.